

Northbrook, Illinois • (847) 272–8800

Melville, New York • (516) 271–6200

Santa Clara, California • (408) 985–2400

Research Triangle Park,
North Carolina • (919) 549–1400

Camas, Washington • (360) 817–5500

## CERTIFICATE OF COMPLIANCE

CERTIFICATE NUMBER: 201097 - BP7019 ISSUE DATE: 20 October 1997

Issued to:

Sargent and Greenleaf Inc. One Security Drive Nicholasville, KY 40356

Report Reference:

BP7019

This is to Certify that

representative samples of:

Delayed Action Timelock, Model 6205

Have been investigated by Underwriters Laboratories Inc. in accordance with the Standard(s) indicated on this Certificate.

Standard(s) for Safety:

UL 887, Delayed Action Time Locks

Additional Information:

Only those products bearing the UL Listing Mark should be considered as being covered by UL's Listing and Follow-Up Service.

The UL Listing Mark generally includes four elements as follows: the name "Underwriters Laboratories Inc." in various forms and type styles, or abbreviations such as "Und. Lab. Inc.", or the symbol "UL in a circle" - (1); the word "Listed"; a control number (may be alphanumeric) assigned by UL: and the product or category name (product identifier), as indicated in the appropriate UL Directory.

LOOK FOR THE UL LISTING MARK ON THE PRODUCT

**Engineer:** 

Underwriters Laboratories Inc. 4.44

agnai a. Liasso

Review Engineer:

Underwriters Laboratories Inc.